

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-002135**Date Inspected:** 25-Apr-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 1330**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 2300**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name:	N/A	CWI Present:	Yes	No			
Inspected CWI report:	Yes	No	N/A	Rod Oven in Use:	Yes	No	N/A
Electrode to specification:	Yes	No	N/A	Weld Procedures Followed:	Yes	No	N/A
Qualified Welders:	Yes	No	N/A	Verified Joint Fit-up:	Yes	No	N/A
Approved Drawings:	Yes	No	N/A	Approved WPS:	Yes	No	N/A
				Delayed / Cancelled:	Yes	No	N/A
Bridge No:	34-0006	Component:	OBG				

Summary of Items Observed:

The Caltrans Quality Assurance (QA) Inspector Charlie Franco was present at the time requested to randomly observe welding and associated operations being performed for the Tower and Orthotropic Box Girders (OBG).

New Tower Shop Bay 1, 2 & 3:

No welding for this contract being performed.

New OBG:

No welding for this contract being performed.

OBG Bay 2, 4, 7 & 8:

No welding for this contract being performed.

OBG Bay 4:

The QA Inspector performed a random Magnetic Particle Testing examination and Visual examination on 10% of the welds attaching the I-Stiffeners to Side Plate SP410-001 Weld Joints SP410-001-001 through 010. There appeared to be no indications. Attached photographs provide additional detail. Please see applicable 6028 for 04-25-2008.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)



Summary of Conversations:

There were no relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Pat Lowry (858) 344-2712, who represents the Office of Structural Materials for your project.

Inspected By: Franco,Charlie

Quality Assurance Inspector

Reviewed By: Carreon,Albert

QA Reviewer